

Page 1 of 3

Date : 10/13/2008

Supervisor : Ryan Lamont

Notifications (Residents, Fire, 311) :
Yes


Notifications (Residents, Fire, 311) :
Yes

LEGEND

- ⊗ SMOKE OBSERVATION
- BLOWER LOCATIONS
- WW_ManholeJunction_1
- WW_Sewer
- SMOKE RUN

Defect Code	Defect Description
SL	Service Lateral
TJ	Transition Joint
DD	Driveway Drain
WVD	Window Well Drain
STRD	Stairwell Drain
AD	Area Drain
DS	Downspout
DSC	Downspout Connection
FD	Foundation Drain

Defect Code	Defect Description
CB	Catch Basin
SD	Storm Ditch
SVMH	Storm Manhole
MAIN	Main Sewer
SANMH	Sewer Manhole
CO	Cleanout
OTHER	Other
IOB	Inside of Building



LEGEND

-

Defect Code	Defect Description
SL	Service Lateral
TJ	Transition Joint
DD	Driveway Drain
WWD	Window Well Drain
STRD	Stairwell Drain
AD	Area Drain
DS	Downspout
DSC	Downspout Connection
FD	Foundation Drain

Defect Code	Defect Description
CB	Catch Basin
SD	Storm Ditch
SWMH	Storm Manhole
MAIN	Main Sewer
SANMH	Sewer Manhole
CO	Cleanout
OTHER	Other
IOB	Inside of Building

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 10/13/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : Ryan Lamont


Manhole ID : S07111008MH

Test ID : S1032-034041

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Cleanout; Smoke: Medium; Status: Public ROW


Landscape



Defect



ID






Location: N/A; Type: Catch Basin; Smoke: Medium; Status: Public ROW

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 3
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>10/13/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>	Ground Condition : Dry : <u>X</u> Damp : <u> </u> Wet : <u> </u>	Supervisor : <u>Ryan Lamont</u>
Manhole ID : <u>S07111008MH</u>	Test ID : S1032-034041	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div>ID</div> <div>  <p>Location: N/A; Type: Service Lateral; Smoke: Light; Status: Private Property</p> </div> <div> <div>Landscape</div> <div>  </div> <div> <div>Defect</div> <div>  </div> </div> </div> </div>		